



## **State Water Resources Control Board**

August 30, 2018

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7018 0680 0000 1017 5031

Mr. Tom Hall
Director, Environmental and Fire Protection
City of Santa Fe Springs
11300 Greenstone Avenue
Santa Fe Springs, California 90670
tomhall@santafesprings.org

SUBJECT:

NOTICE OF VIOLATION - NO FURTHER ACTION REQUIRED;

UNDERGROUND STORAGE TANK SYSTEMS AT SANTA FE SPRINGS FIRE RESCUE STATION #1, 11300 GREENSTONE AVENUE, SANTA FE SPRINGS

Dear Mr. Hall:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the UST(s) at your facility on August 17, 2018, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and California Code of Regulations (CCR), title 23, chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Monitor Product Piping – The sensor located inside the diesel fill sump was unable to detect a leak at the earliest opportunity because the sensor was located on the wrong side of the sump. Corrected at the time of inspection.	Diesel	August 17, 2018	August 17, 2018	23 CCR 2630(d)
2	Failure to Tag Monitoring Equipment – An annual monitoring certification tag was not affixed to the UST monitoring system panel. Corrected at the time of inspection.	All	August 17, 2018	August 17, 2018	23 CCR 2638(f)

Office of Enforcement | 801 K Street, Suite 2300 | Sacramento, CA 95814 | 916.341.5272

FELICIA MARCUS, CHAIR | EILEEN SOBECK, EXECUTIVE DIRECTOR

To our knowledge, the violations above have been corrected. Therefore, no further action is required at this time. The State Water Board reserves the right to bring an action against the owner and/or operator of the tanks in violation, or it may recommend that Santa Fe Springs Fire-Rescue pursue enforcement, or Santa Fe Springs Fire-Rescue may elect to pursue enforcement independently.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel

Senior Environmental Scientist

**UST Enforcement Unit** 

Office of Enforcement

cc: (via email only)

Ms. Brenda ten Bruggencate

**Deputy Director** 

**Environmental Services** 

Santa Fe Springs Fire-Rescue

brendanelson@santafesprings.org